

US EPA ARCHIVE DOCUMENT

<b>UNIT LOG</b>	1. Incident Name Kalamazoo River/Enbridge Oil Spill	2. Date Prepared 11/30/2012	3. Time Prepared 1800
4. Unit Name/Designators Situation Unit	5. Unit Leader (Name and Position) Melinda Luetke, Planning Section Chief		6. Operational Period 0700, 11/27/2012 – 0700, 12/10/2012
7. Personnel Roster Assigned			
Name		ICS Position	Home Base
Larry Rader		Situation Unit Leader	Chicago, IL
8. Activity Log			
Time	Major Events		
09:30	<ul style="list-style-type: none"> <li>Arrived at C0.4 boat launch.</li> <li>No sheen observed in vicinity of trestle above Ceresco Dam. Bank ice observed along RDB on downstream side of trestle.</li> <li>No sheen, some debris observed within Ceresco Dam containment boom.</li> <li>Ceresco Dam control point, observed bathymetry survey crews operating along LDB below trestle and RDB above Dam.</li> </ul>		
11:30	<ul style="list-style-type: none"> <li>Morrow Lake Delta, observed pontoon boat lodged on island in delta following removal of anchor at this location. Crews were working to free boat from location and move it to next anchor location.</li> </ul>		
13:00	<ul style="list-style-type: none"> <li>MP 36.5 RDB, spontaneous sheen trail and tar globules observed coming out of wetland area along RDB and moving downstream to just west of 35<sup>th</sup> Street Bridge. Operations was notified and a sheen sweeper boat was deployed.</li> </ul>		
14:00	<ul style="list-style-type: none"> <li>MP 15.5 RDB, steady spontaneous sheen trail observed coming out of back water area in South Mill Pond and entering river channel south of Burnham Street Bridge. Operations was notified, and recovery activities including a sheen sweeper boat and boom deployment were initiated.</li> </ul>		
15:00	Returned to ICP.		
9. Prepared by (Name and Position) Larry Rader, Situation Unit Leader, USEPA-START			